

S0190064
Task ID# 1825

Black Gold Organic Fertilizer Inc
3802 47th
Lubbock Tx 79413

Task # 1782,50190064, Grand County, Utah
Entity# 6545503-0143

State of Utah
Department of Natural Resources
Division of Oil Gas and Mining
Susan M. White
Mining Program Coordinator
Minerals Regulatory Program

Subject: Deficient Notice of Intention to Commence Small Mining Operations, Black Gold Organic Fertilizer Inc, Rhea Rae Mine, Task 1782, S0190064, Grand County, Utah

Dear Ms. White:

Black Gold Organic Fertilizer would like to address the comments of your letter of April 27, 2007.

With respect to items 1 and 2, see **ATTACHMENT NO. 1**, Notice of Intention to Commence Small Mining Operations. Note **ENTITY NO. ITEM NO. 2**. Also, please find **CERTIFICATE OF ACCOUNT STATUS** from Texas Comptroller of Public Accounts to Black Gold Organic Fertilizer Inc is in good standing. Also, please find State of Utah Dept of Commerce **APPLICATION FOR AUTHORITY TO CONDUCT AFFAIRS FOR FOREIGN CORPORATION**. Fees paid-Date of Incorporation is 2/11/1983.

In reply to item number three, please see **ATTACHMENT NO. 2**. This schematic clearly shows the mill work area affected. The tailing pond liquids will be recycled back into processing system to help concentrate the fertilizer value, plus aid in the break down process of the ore. We have large bladders to contain portion of this process. This will be a very efficient plant in all faciates. For general understanding, no other companies in the USA or Canada are doing what we are attempting. Our process is not harmful, yet will benefit many. This attachment also addresses question number 7 and the processing equipment is **ATTACHMENT NO. 3** is pretty much like the panjon system of extraction only it has no bad chemicals. No tailing will leave this location unless they are to be processed into some unforeseen item or material. Number 4 was misinformation , no Sodium Hydroxide or Sodium Chloride will be used. The answer to item No 6 is a closed system with a settling pond and 20,000 gallon bladders are in the current design. Item number 8 , no permanent foundations are to be built.

RECEIVED

MAY 17 2007

DIV. OF OIL, GAS & MINING

See ATTACHMENT NO 3 for equipment to be used. This total process is a Trade Secerate. That's why no one is doing either. We have a research and development department that is to recycle and find any revenues from the process we are exposed to.

This plant is highly technical, and time is of great importance to get constructed and have the engineers, chemists, and designers the opportunity to complete and work out any problems to allow product and revenue to be produced. We are quite anxious to get started. We will contact the Division of Water. We have been in contact with them concerning a possible water well, and as well, we will do whatever is required by our lease.

If you have any questions concerning this letter, please contact me at 806-928-9406.

Sincerely,



Darrell G. Boepple
Black Gold Fertilizer Inc
Secretary/Treasurer

Cc: Paul Baker
Will Stokes